

## TallyGenicom TechNote GEN\_T\_012

**Parallel Port is not Functional** - Models 2265 / 2280, 3116, 7265, LA650 / LA800

**Issue / Symptom:** The Parallel Port does not Function.

**Procedure:**

The parallel port is not functional when a TallyCom+ IIF-4 Ethernet card is installed in the printer. The TallyCom+ utilizes a parallel interface connection internal to the printer.

**Additional Notes/Comments:**

Need help? Call our knowledgeable sales staff at: [1-800-243-3338](tel:1-800-243-3338)