

Tally® T2365 versus GENICOM® 3860

T2365



3860



Tally® T2365

GENICOM® 3860

Print head design and rated life		
Pins	24	18
Life (Mil Chars)	750	750
Speed (Characters per Inch)		
Draft 10 cpi	640	600
Draft 12 cpi	800	720
NLQ 10 cpi	180	175
NLQ 12 cpi	215	180
Interfaces		
Parallel	Standard	Standard
Serial	Available	Standard
Ethernet	Standard	Available
IBM® Coax SCS Option	Yes	Yes
IBM® Twinax SCS Option	Yes	Yes
IBM® Coax IPDS Option	Yes	Yes
IBM® Twinax IPDS Option	Yes	Yes
IGP/QMS Graphics Option	Yes	Yes
Emulations		
Standard Emulation Set	IBM® Proprinter, Epson® LQ (ESC P/2), GENICOM® ANSI, MTPL +	ANSI X3.64, GENICOM® 3410, Epson® FX286e, DEC LA210, IBM® Proprinter III XL
Paper		
Auto Parking	Yes	Yes
Zero Tear	Yes	Yes
Paper Drive	Push Tractor	Push Tractor
Type	Continuous Forms, Multi-part Forms	Continuous Forms, Multi-part Forms
Paper Path Auto Switching	Yes	Yes
No. of copies	Up to 8 + original	Original + 6
Reliability		
MTBF @ 25% duty cycle	12,500 Hours	10,000 Hours
Standard Ribbon		
	20 Million Characters	15 Million Characters - not available
Current Production		
	Yes	No
Current Manufacturer New Buy Warranty		
	90 Day On-Site	Not Available
Current Manufacturer Try It, Buy It Program		
	Yes	No longer manufactured
Energy Star Certified		
	Yes	Yes



A Consultex, Inc. company since 1987

The Printer Place

2140 South Dupont Drive Anaheim, CA 92806
(800) 243-3338
www.theprinterplace.com



www.dascomamericas.com - makers of Tally T2365

*NOTE - GENICOM ribbons were discontinued in 2017 by their manufacturer with no secondary source for ribbons due to their patented technology.